



EQUIPMENT SAFETY INSPECTION & REPAIR REPORT

Company: Trumanagement Services LLC

Location: 2901 Beacon Rd, Amarillo, TX 79118

Equipment brand: Komatsu

Equipment model: WA270-7 Wheel Loader

Equipment year: 2014 Hour Meter: 6,100

Equipment serial #: KMTWA122J36A27099

N/A = NOT APPLICABLE

OK = NO REPAIRS NEEDED

RR = REQUIRES REPAIR

N/A OK RR

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	General condition
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Engine Condition
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Visible leaks
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Visible engine fails
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Exhaust
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Battery
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Air filter
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Tyres/Tracks
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Oil level/pressure

N/A OK RR

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Steering
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Coolant Level
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Brakes
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Hydraulic Oil Level
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Hydraulic controls
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Lifting Mechanism
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Fire extinguisher
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Lights
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Backup Alarm

Expansion of defects

Full inspection carried out. No leaks were found, and also no faults: none of the instrument panel lights indicates any problem.

They all go off after engine starts running.

Oil and filters changed, this equipment is ready to work.

Mechanic's Signature: 

Date: 11/27/2024



TRUMANAGEMENT SERVICES LLC
2901 Beacon Rd, Amarillo, TX 79118