



EQUIPMENT SAFETY INSPECTION & REPAIR REPORT

Company: Trumanagement Services LLC

Location: 2901 Beacon Rd, Amarillo, TX 79118

Equipment brand: John Deere

Equipment model: 350G LC Excavator

Equipment year: 2014 Hour Meter: 5,114

Equipment serial #: 1FF350GXCEE810076

N/A = NOT APPLICABLE

OK = NO REPAIRS NEEDED

RR = REQUIRES REPAIR

N/A OK RR

☒	☒	☐	General condition
☒	☒	☐	Engine Condition
☒	☐	☐	Visible leaks
☒	☐	☐	Visible engine fails
☐	☒	☐	Exhaust
☐	☒	☐	Battery
☐	☒	☐	Air filter
☐	☒	☐	Tyres/Tracks
☐	☒	☐	Oil level/pressure

N/A OK RR

☒	☒	☐	Steering
☒	☒	☐	Coolant Level
☒	☒	☐	Brakes
☒	☒	☐	Hydraulic Oil Level
☒	☒	☐	Hydraulic controls
☒	☒	☐	Lifting Mechanism
☒	☒	☐	Fire extinguisher
☒	☒	☐	Lights
☒	☒	☐	Backup Alarm

Expansion of defects

Full inspection carried out. No leaks were found, and also no faults: none of the instrument panel lights indicates any problem.

They all go off after engine starts running.

Oil and filters changed, this equipment is ready to work.

Mechanic's Signature: _____



Date: 11/27/2024



TRUMANAGEMENT SERVICES LLC
2901 Beacon Rd, Amarillo, TX 79118